



ਕਾਰਜਕਾਰੀ ਇੰਜੀਨੀਅਰ, ਉਸਾਰੀ ਮੰਡਲ ਨੰ:2

ਲੋਕ ਨਿਰਮਾਣ ਵਿਭਾਗ (ਭ ਤੇ ਮ) ਸ਼ਾਖਾ, ਬਠਿੰਡਾ।

email: - xene2bill@gmail.com

ਫੋਨ ਨੰ: 0164-2212428

ਮੀਮੋ ਨੰ: 963

ਮਿਤੀ: 23/05/24

ਵੱਲ

ਪ੍ਰੀਮੀਪਲ
ਦੁਸ਼ਕਾਰ ਸਕੂਲ,
ਤਲਵੰਡੀ ਸਾਥੇ।

ਵਿਸ਼ਾ

ਬਿਲਡਿੰਗ ਸੇਫਟੀ ਸਰਟੀਫਿਕੇਟ ਜਾਰੀ ਕਰਨ ਸਬੰਧੀ (ਸਾਲ 2024-25)

ਹਵਾਲਾ

ਆਪ ਦਾ ਪੱਤਰ ਨੰ. -140 ਮਿਤੀ 31.03.2024 ਦੇ ਸਬੰਧ ਵਿੱਚ।
ਉਪਰੋਕਤ ਵਿੱਚ ਅਤੇ ਹਵਾਲੇ ਆਪਿਨ ਪੱਤਰ ਰਾਈ ਆਪ ਵੱਲ ਵਿੱਚ ਅੰਕਿਤ ਸਕੂਲ ਦੀ ਇਮਾਰਤ ਦਾ ਬਿਲਡਿੰਗ ਸੇਫਟੀ ਸਰਟੀਫਿਕੇਟ
ਸਾਲ 2024-25 ਲਈ ਆਪ ਵੱਲ ਇਸ ਦਫਤਰ ਵਿੱਚ ਪ੍ਰਾਪਤ ਹੋਇਆ ਹੈ। ਆਪ ਦੇ ਸਕੂਲ ਦੀ ਬਿਲਡਿੰਗ ਦੀ ਉਪ ਮੰਡਲ ਇੰਜੀਨੀਅਰ ਦੇ ਦਫਤਰ ਵੱਲ
ਵਿੱਚਾਲੇ ਇੰਸਪੇਕਸ਼ਨ ਕੀਤੀ ਗਈ ਅਤੇ ਉਨ੍ਹਾਂ ਦੀ ਰਿਪੋਰਟ/ਸਿਫਾਰਿਸ਼ ਅਨੁਸਾਰ ਨਿਮਨਲਿਖਤ ਨਿਰੀਖਣ ਅਤੇ ਸੁਰਤਾਂ ਆਪਿਨ ਸਾਲ 2024-25 ਦਾ ਸਕੂਲ
ਬਿਲਡਿੰਗ ਸੇਫਟੀ ਸਰਟੀਫਿਕੇਟ ਮਿਤੀ 31.03.2025 ਤੱਕ ਜਾਰੀ ਕੀਤਾ ਜਾਂਦਾ ਹੈ।

- 1 ਸਕੂਲ ਕੇਲ ਕਿਸੇ ਅਟਮੂਖਾਵੀ ਘਟਨਾ ਨਾਲ ਨਜ਼ਿੰਠਣ ਲਈ ਯੋਜਨਾ ਹੋਈ ਚਾਹੀਦੀ ਹੈ, ਜਿਸ ਵਿੱਚ ਐਮਰਜੈਂਸੀ ਦੌਹਾਨ ਬੰਚਿਆਂ ਨੂੰ ਬਿਲਡਿੰਗ
ਵਿੱਚੋਂ ਸੁਰੱਖਿਅਤ ਬਾਹਰ ਵੱਚਣ ਅਤੇ ਸਬੰਧਤ ਵਿਭਾਗ ਨਾਲ ਤਲਸਮੇਲ ਕਰਨ ਦੀ ਯੋਜਨਾ ਹੋਈ ਚਾਹੀਦੀ ਹੈ। ਸਕੂਲ ਨੂੰ ਇਸ ਯੋਜਨਾ ਦੀ
ਪ੍ਰਤਾਪਦੀਤਤਾ ਨੂੰ ਯਕੀਨੀ ਬਣਾਉਣ ਲਈ ਨਿਯਮਿਤ ਤੌਰ 'ਤੇ ਸਮੀਖਿਆ ਅਤੇ ਅਪਡੇਟ ਕਰਦੇ ਰਹਿਣਾ ਚਾਹੀਦਾ ਹੈ।
- 2 ਜੇਕਰ ਸਕੂਲ ਵੱਲ ਇਸ ਇਮਾਰਤ ਵਿੱਚ ਕੋਈ ਵਾਧਾ, ਤਬਦੀਲੀ, ਵਿਸਤਾਰ ਅਤੇ ਸੋਧ ਦੀ ਲੋੜ ਹੈ ਜਾਂ ਕੀਤੇ ਜਾਣੇ ਹਨ ਤਾਂ ਇਸ ਦਫਤਰ ਦੀ ਤੁਰੰਤ
ਜਾਂਚ ਦਾ ਪ੍ਰੰਤੀ ਕੀਤਾ ਜਾਣਾ ਚਾਹੀਦਾ ਹੈ ਅਤੇ ਉਸ ਵਿੱਚੋਂ ਨੂੰ ਮੁਕੰਮਲ ਕਰਕੇ ਉਸ ਦਾ ਸੇਫਟੀ ਸਰਟੀਫਿਕੇਟ ਇਸ ਦਫਤਰ ਪਾਸੋਂ ਫਿਰ ਤੋਂ ਲਿਆ
ਜਾਂਦੇ।
- 3 ਜੇਕਰ ਬਿਲਡਿੰਗ ਦੀਆਂ ਕੰਪਾਂ, ਨੀਂਹਾਂ ਅਤੇ ਛੱਤਾਂ ਤੁਦਰਤੀ ਆਵਤ ਜਾਂ ਕਿਸੇ ਹੋਰ ਕਾਰਨ ਕਰਕੇ ਥੋੜ੍ਹਾ ਜਾਣ ਤਾਂ ਇਸ ਸ਼ੁਰੂ ਵਿੱਚ ਸਕੂਲ ਵੱਲੋਂ ਇਸ
ਦਫਤਰ ਨੂੰ ਤੁਰੰਤ ਬਿਲਡਿੰਗ ਦੀ ਹਾਲਤ ਬਾਰੇ ਸੁਚਿਤ ਕੀਤਾ ਜਾਵੇ ਅਤੇ ਨਿਰੀਖਣ ਕਰਵਾਉਣ ਉਪਰਾਂ ਦੀ ਬਿਲਡਿੰਗ ਨੂੰ ਵਹਤੋਂ ਵਿੱਚ ਲਿਆ ਜਾਵੇ।
- 4 ਸਬੰਧਤ ਵਿਭਾਗ ਤੋਂ ਵੱਖਰੇ ਤੌਰ 'ਤੇ ਫਾਈਰ ਸੇਫਟੀ ਸਰਟੀਫਿਕੇਟ, ਇਕੱਲਕਟੀਵ ਸੇਫਟੀ ਸਰਟੀਫਿਕੇਟ ਪ੍ਰਾਪਤ ਕੀਤਾ ਜਾਵੇ।
- 5 ਸਕੂਲ ਬਿਲਡਿੰਗ ਦੀ ਸੇਫਟੀ ਨੂੰ ਮੁੱਖ ਰੱਖਦੇ ਹੋਏ ਬਿਲਡਿੰਗ ਦੀ ਰਿਪੋਰਟ ਕਰਵਾਉਣ ਦੀ ਲੀਗੋਵਾਰੀ ਸਕੂਲ ਪ੍ਰੰਤੀਨ ਦੀ ਹੈ। ਇਸ ਰਿਪੋਰਟ ਦੇ
ਬਾਵਜੂਦ ਸਕੂਲ ਪ੍ਰੰਤੀਨ ਸਾਰੇ ਪੱਧੇ ਤੇ ਬਿਲਡਿੰਗ ਦੀ ਗੁਰੋਧਾ ਲਈ ਸਿੰਗੇਵਰ ਹੈ।
- 6 ਸਕੂਲ ਨੂੰ ਸਟਾਫ ਮੈਂਬਰਾਂ ਨੂੰ ਸੁਚਿਤ ਸੁਰੱਖਿਆ ਸਿਖਲਾਈ ਪ੍ਰਦਾਨ ਕਰਨੀ ਚਾਹੀਦੀ ਹੈ, ਜਿਸ ਵਿੱਚ ਐਮਰਜੈਂਸੀ ਫਲਾਈ ਏਂਡ ਅਤੇ ਨਿਕਾਸੀ ਪ੍ਰੋਟੋਕੋਲ
ਨੂੰ ਸੰਚਾਲਣ ਦੀਆਂ ਪ੍ਰਕਿਰਿਆਵਾਂ ਵੀ ਸ਼ਾਮਲ ਹਨ।
- 7 ਸਕੂਲ ਦੇ ਕਵਰਡ ਏਂਕੇਈ ਦੇ ਹਿਆਂ ਨਾਲ ਜੀਅਅਰ, ਨੰ: 1744907 ਰਾਹੀਂ ਦਸ ਹਜ਼ਾਰ ਰੁਪਏ (10,000/-) ਬਿਲਡਿੰਗ ਨਿਰੀਖਣ ਫੀਸ ਵਾਲੇ
ਪ੍ਰਾਪਤ ਕੀਤੇ। ਸਕੂਲ ਦਾ ਫਾਈਰ ਸੇਫਟੀ ਸਰਟੀਫਿਕੇਟ 10.12.2024 ਤੱਕ ਵੈਲਿਡ ਹੈ ਅਤੇ ਸਕੂਲ ਪ੍ਰੰਤੀਨ ਸਮੇਂ ਸੀਮਾ ਅੰਦਰ ਫਾਈਰ ਸੇਫਟੀ
- 8 ਸਰਟੀਫਿਕੇਟ ਨੀਨਿਊ ਕਰਵਾਉਣ ਲਈ ਸਿੰਗੇਵਰ ਹੋਵੇਗਾ।
- 9 ਇਹ ਰਿਪੋਰਟ ਕਾਨੂੰਨੀ ਉਦੇਸ਼ ਲਈ ਵੈਲਿਡ ਨਹੀਂ ਹੈ।

ਸਕੂਲ ਦਾ ਫਾਈਰ ਸੇਫਟੀ ਸਰਟੀਫਿਕੇਟ 10.12.2024 ਤੱਕ ਵੈਲਿਡ ਹੈ। ਜੇਕਰ ਸਕੂਲ ਪ੍ਰੰਤੀਨ ਵੱਲੋਂ ਫਾਈਰ ਸੇਫਟੀ ਸਰਟੀਫਿਕੇਟ
ਮਿਤੀ 31.03.2025 ਤੱਕ ਲਈ ਗੱਲਿਊ ਕਰਵਾ ਲਿਆ ਜਾਂਦਾ ਹੈ ਤਾਂ ਬਿਲਡਿੰਗ ਸੇਫਟੀ ਸਰਟੀਫਿਕੇਟ (ਬਿਨਾਂ ਦੁਆਰਾ ਇੰਸਪੇਕਸ਼ਨ ਫੀਸ ਜਾਮ੍ਹਾਂ
ਕਰਵਾਏ) ਮਿਤੀ: 31.03.2025 ਤੱਕ ਵੈਲਿਡ ਨਹੀਂ ਹੈ।

ਪਿੱਠ ਅੰਕਣ:-

ਉਪਰੋਕਤ ਦਾ ਉਤਾਰਾ ਉਪ ਮੰਡਲ ਇੰਜੀਨੀਅਰ, ਪ੍ਰਾਤਕ ਉਪ ਮੰਡਲ ਨੰ. 4 ਤੇ ਮ ਸ਼ਾਖਾ ਤਲਵੰਡੀ ਸਾਥੇ ਨੂੰ ਉਹਨਾਂ ਦੇ ਪੱਤਰ ਨੰ. 66
ਮਿਤੀ 16.05.2024 ਦੇ ਸਬੰਧ ਵਿੱਚ ਕੇ ਲਿਆਂਦਾ ਹੈ ਕਿ ਆਪ ਦੀ ਸਿਫਾਰਿਸ਼ ਨੂੰ ਮੁੱਖ ਰੱਖਦੇ ਹੋਏ ਉਕਤ ਸਕੂਲ ਨੂੰ ਬਿਲਡਿੰਗ ਸੇਫਟੀ ਸਰਟੀਫਿਕੇਟ

Deep Principal
The Sanskaar School
Talwandi Sabo

ਕਾਰਜਕਾਰੀ ਇੰਜੀਨੀਅਰ
ਉਸਾਰੀ ਮੰਡਲ ਨੰ: 2 ਤੱਤੇਮ ਸ਼ਾਖਾ
ਬਠਿੰਡਾ।

ਮਿਤੀ:-
ਕਾਰਜਕਾਰੀ ਇੰਜੀਨੀਅਰ
ਉਸਾਰੀ ਮੰਡਲ ਨੰ: 2 ਤੱਤੇਮ ਸ਼ਾਖਾ
ਬਠਿੰਡਾ।

(Punjabi to English Translation)


Executive Engineer, Construction Board No:2

Public Works Department (P.W.D) Branch Bathinda.

e-mail: xenc2bt@omall.com
Phone and Fax: 0164-2212428
Date: 23/05/24

Memo No: 963

To
The Principal
The Sanskaar School
Talwandi Sabo




Subject Regarding Issuance of Building Safety Certificate (Session 2024-25)
Reference with respect to your letter no. 140 dated 31.03.2024 is has been received by you at this office to obtain the building safety certificate for the year 2024-25 of the school building under the above subject and reference. A visual inspection of your school building has been done by the office of the Sub Divisional Engineer and as per their report/recommendation the School Building Safety Certificate for the year 2024-25 is issued up to 31.03.2025 subject to the following terms and conditions: -

1. The school should have a plan to deal with an untoward incident, including the safe evacuation of children from the building during an emergency and a plan to coordinate with the concerned department. The school should regularly review and update this plan to ensure its effectiveness.
2. If any addition, alteration, extension or modification is required to be made by the school in this building, immediate inspection should be arranged by this office and the safety certificate thereof should be obtained again from this office after completion of that part.
3. If the walls, foundations and roofs of the building collapse due to natural calamity or any other reason, then the school should immediately inform this office about the condition of the building and the building should be put into use only after conducting an inspection.
4. Fire safety certificate, electrical safety certificate should be obtained separately from the concerned department.
5. The school management is responsible for repairing the building keeping the safety of the school building in mind. Despite this report, the school management is responsible for the security of the building in all respects.
6. Letter NA-80/24 dated 27.04.2024 from Next Architects, Mansa has given Structure Safety Certificate and as per their certificate the school is safe for use for session 2024-25, but this school is not constructed by this department. Therefore, the safety of the school structure especially from the earthquake point of view cannot be ensured by this department.
7. The school must provide staff members with appropriate safety training, including procedures for handling emergency first aid and evacuation protocols.
8. According to the covered area of the school, G.R. Received ten thousand rupees (10,000/-) as building inspection fee through No: 1744907. The fire safety certificate of the school is valid till 10.12.2024 and the school management will be responsible for renewing the fire safety certificate within the time limit.
9. This report is not valid for legal purpose.

The fire safety certificate of the school is valid till 10.12.2024. If the fire safety certificate is renewed by the school management upto 31.03.2025, then the building safety certificate (without re-submission of inspection fee) will be considered valid till 31.03.2025.

Attested to be True Translation
from : Punjabi To : English



Executive Engineer
Construction Division No:2
Bhutom Branch:
Bathinda

Copy of the above to the Sub Divisional Engineer, Provincial Sub Division No.4 B and M Branch Talwandi Sabo vide his letter no. 66 dated 16.05.2024, it is written that building safety certificate is issued to the said school keeping your recommendation in mind.

Executive Engineer
Construction Division No:2
Bhutom Branch
Bathinda

ATTESTED

SARBJIT SINGH
Advocate & Notary
TALWANDI SABO
14/06/2024

Principal
The Sanskaar School
Talwandi Sabo